

Evidence # 2

Von Ah compost application

Photos from Andrew & Julie Austin

All flood photos taken on 10 Oct 2025, showing the extent of waterways & Duck Creek flooding



Photo 1 – Duck Creek flooded - taken from the entrance of Von Ah Contracting from 1047 Kaniere Kowhitrangi Road.



Photo 2 – showing waterways on Von Ah farm, taken from Kaniere-Kowhitrangi road near the entrance to the proposed compost plant.



Photo 3 – Duck Creek- taken from upper Kokatahi road near the school



photo 4 - Duck Creek flooded - taken from the entrance of Von Ah Contracting from 1047 Kaniere Kowhitrangi road.



Photo 5 - looking at the applicant's neighbour's property 2 Upper Kokatahi Road -



photo 6 – comparison with photo 5 (taken 16th Feb 2026)



photo 7 - Comparison Duck Creek of photo 4 (taken 18 Feb 26)



photo 8 - Comparison Duck Creek of photo 4 (taken 18 Feb 2026)



Photo 9 – Comparison of waterways photo 2 (taken 18 Feb 26)